


I-144B/I-144G PARTS LIST

Stingray Adjustable

Small 12-2
Medium 3-6



Part #	Description	Cost	Qty	Total	Part #	Description	Cost	Qty	Total
410	Female Axle				BF7282P	Wheel - 72mm Purple			
832	Male Axle Screw				3244O	Strap/Lever Orange/Grey			
835	Bearing Alignment Insert				3244P	Strap/Lever Purple/White			
775	Bearing Spacer				413W	Heel Stop - White			
608B7	Bearing - Rated 7				412W	Heel Stop Bracket White			
744/745	Male Heel Stop Screw				413B	Heel Stop - Black			
411	Female Axle (Brake)				412	Heel Stop Bracket Black			
BF7282O	Wheel - 72mm Orange								

All orders must be paid by check, Visa, or Mastercard prior to shipment
All orders are required to be faxed or mailed with signature

CA residents add 8% tax
IL residents add 6.75% tax
PA residents add 6% tax

Subtotal	
Tax	
Shipping and Handling	\$6.25
TOTAL	

Name: _____ Signature: _____ Phone: _____

Address: _____ City: _____ State: _____ Zip: _____

MC or Visa #: _____ Exp Date: _____

1. Check the axle screws on each wheel. The male and female should be tightened firmly prior to each use.
2. Check heel stop screw before skating. The male and female should be tightened firmly. If heel stop shows substantial wear, it should be replaced.
1. Sur chaque roue, vérifiez les vis de l'essieu. Les vis mâles et femelles doivent être serrées fermement avant l'utilisation des patins.
2. Vérifiez les vis du frein avant l'utilisation des patins. Les vis mâles et femelles doivent être serrées fermement. Si le frein arrière montre des signes apparents d'usure. Veuillez le remplacer.

1. Prüfen sie die schrauben aller rollen, schraube und mutter vor gebrauch gut festdrehen.
2. Prüfen sie die schraube beim stopper bevor sie fahren. Schraube und mutter gut befestigen. Ersetzen sie den stopper, wenn er abgenutzt ist.
1. Cheque los tornillos de cada rueda, macho y hembra de los tornillos deberan apretarse antes de cada uso.
2. Cheque todos los tornillos del freno para asegurarse que esten bien apretados. Si nota que la goma del freno esta gastada, esta debera ser reemplazada por una nueva